

TRACK INSPECTION REPORTING FORM

Name Billard, Greenwood Date 8-26-2013 Page 1 of 1
 (Please Print)
 Watchman Nelson W.O Number 1193143
 Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.	<u>768</u>			<u>1</u>	<u>W</u>		<u>M308</u>	<u>348</u>	<u>Y</u>	<u>N</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	<u>hairline crack in weld of the rail 5/16" x 1/4" on side of rail head and across</u>
2	<u>two burn marks 1/4" deep on top of rail, caused by catenary wire striking rail.</u>
3	<u>burn mark at base of rail cause catenary striking rail</u>

Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 Yes NO

SPECIAL INSPECTION Yes NO

Reason for special Inspection ?

Track Inspector Signature

Michael L. Ballard

Supervisory Certification

M. Ballard



Work Order Tracking (Tr)

Find:

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting

Work Order Site
Asset Alias

Children of Work Order 1193143

Tasks for Work Order 1193143

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	MPOLLARD	<input checked="" type="checkbox"/>	08/26/13	07:00:00
<input type="text"/>	WGREENWOOD	<input checked="" type="checkbox"/>	08/26/13	07:00:00
<input type="text"/>	RNELSON1	<input checked="" type="checkbox"/>	08/26/13	07:00:00

TRACK INSPECTION REPORTING FORM

Name W. Bryant Date 08-27-13 Page 1 of 1

(Please Print)

Watchman D. Boyd W.O Number 1194927
Inspected From Lutherville To Cold Spring

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	359+42	1	—	1	E/W	—	W-301	332	Y	H
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	A + CM 359+42 - N. track 1. South of the high block at Fall Road STA. 8-ties are pumping. 12" under load. the area is marked yellow.

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification



Work Order Tracking (Tr)

Find:

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reportin

Work Order Site
Asset Alias

Children of Work Order 1194927

Tasks for Work Order 1194927 1 - 2 of 2

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor 1 - 1 of 1

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	<input type="text" value="WBRYANT"/>	<input checked="" type="checkbox"/>	<input type="text" value="08/27/13"/>	<input type="text" value="06:00:00"/>

TRACK INSPECTION REPORTING FORM

Name Boillard Date 8-27-2013 Page 1 of 1

Watchman (Please Print) Greenwood Penn Line W.O Number 1195058

Inspected From Coltsprings To Camden yards

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO

SPECIAL INSPECTION Yes _____ NO

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification



Work Order Tracking (Tr)

Find: Select Action

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting

Work Order Site
Asset Alias

Children of Work Order 1195058 Filter >

Tasks for Work Order 1195058 Filter >

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor Filter >

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	MPOLLARD	<input checked="" type="checkbox"/>	08/27/13	07:00:00
	WGREENWOOD	<input checked="" type="checkbox"/>	08/27/13	07:00:00

TRACK INSPECTION REPORTING FORM

Name W. Bryan +

Date 08-28-13

Page 1 of 1

(Please Print)

Watchman

R. Mel Sott

W.O Number

1194279

Inspected From

Candler

To

Linthicum

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	<u>42400</u>	<u>-</u>	<u>-</u>	<u>1</u>	<u>W</u>	<u>-</u>	<u>M-311</u>	<u>301</u>	<u>Y</u>	<u>N</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	<u>At Hamburg St STA. CM 42400 - South. the CPSS walk</u> <u>GM 1-track, the end plate was cut OFF. Remove</u> <u>to prevent a tripping hazard.</u>

Were Switch in the area of Inspected

Yes ☒

NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☐

SPECIAL INSPECTION

Yes ☐

NO ☒

Reason for special Inspection ?

Walter W. Bryant

Track Inspector Signature

Supervisory Certification



Work Order Tracking (Tr)

Find:

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting

Work Order Site
 Asset Alias

Children of Work Order 1194279 | Filter >

Tasks for Work Order 1194279 | Filter > 1 - 2 of 2

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor | Filter > 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	RNELSON	<input checked="" type="checkbox"/>	08/28/13	06:00:00
<input type="text"/>	WBRYANT	<input checked="" type="checkbox"/>	08/28/13	06:00:00

TRACK INSPECTION REPORTING FORM

Name

Rollard Greenwood

Date _____

8-28-2013

Page 2 of 2

Watchman

Inspected From

Cromwell yard

To

W.O Number

1194282

[illegible]

Item

COMMENTS

No new defects found

Yard inspection complete

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature
Michael L. Collier

Supervisory Certification

[Signature]

TRACK INSPECTION REPORTING FORM

Pollard

8-28-2013

Page 1 of 2

Please Print) Greenwood

1194282

Leithicum

Crs in we H

[illegible]

COMMENTS

Track inspection complete

NO New defects Found

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification



Work Order Tracking (Tr)

Find:

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting

Work Order Site
 Asset Alias

Children of Work Order 1194282

Tasks for Work Order 1194282 1 - 2 of 2

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	MPOLLARD	<input checked="" type="checkbox"/>	08/28/13	07:00:00
<input type="text"/>	WGREENWOOD	<input checked="" type="checkbox"/>	08/28/13	07:00:00

TRACK INSPECTION REPORTING FORM

Name

Pollard, Greenwood

Date _____

8-29-2013

Page 1 of 1

of l

Watchman

(Please Print)

Please Print) Rahette

Inspected From

Lotherville

To

Gold Springs

W.O Number 1193140

1193140

[illegible]

Item	COMMENTS
------	----------

No new defects noted

Track inspection complete

Were Switch In the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION

Yes

NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature
Michael L Ballard

Supervisory Certification

on M. Rayk

Work Order Tracking (Tr)

List	Work Order	Plans	Actuals	Related Records	Safety Plan
------	------------	-------	---------	-----------------	-------------

Children of Work Order 1193140 Filter      

Tasks for Work Order 1193140 Filter 1 - 2 of 2

Sequence	Task	Summary
10	10	ESTABLISH ON TRACK SAFETY PER RPW
20	20	INSPECT TRACK PER BALT LR STANDARDS

Labor Materials Services Tools Repair Orders

Labor **Filter** 1 - 3 of 3

	Task	Labor	Approved?	Start I
▶		MPOLLARD 	<input checked="" type="checkbox"/>	08/29/
▶		WGREENWOOD 	<input checked="" type="checkbox"/>	08/29/
▶		ARABETTE 	<input checked="" type="checkbox"/>	08/29/

TRACK INSPECTION REPORTING FORM

Name W. Bryant Date 08-29-13 Page 1 of 1

(Please Print)
 Watchman R. NELSON W.O Number 1193133
 Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
1	TK 2, Cm 900+50 - North. At the South end of the high block, both ends of the crosswalk, there are a total of 11-ties that are pumping 1/2" under load. The area is mark in yellow. (Hunt Valley STA).

Were Switch in the area of Inspected Yes ☒ NO ☐
 Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ?

Walter Bryant

Track Inspector Signature

Supervisory Certification

[Signature]



Work Order Tracking (Tr)

Find:

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting

Work Order Site
Asset Alias

Children of Work Order 1193133

Tasks for Work Order 1193133 1 - 2 of 2

Sequence	Task	Summary	Component
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>

Labor Materials Services Tools Repair Orders

Labor 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time
<input type="text"/>	RNELSON	<input checked="" type="checkbox"/>	08/29/13	06:00:00
<input type="text"/>	WBRYANT	<input checked="" type="checkbox"/>	08/29/13	06:00:00

TRACK INSPECTION REPORTING FORM

Name K. Nelson

Date 8-30-13

Page / of /

(Please Print)

(Please Print)
W. Bryant

W.O Number 1193006

165

مکمل کی جاتی ہے۔

[illegible]

Item	COMMENTS
------	----------

No New Defects Noted

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

SPECIAL INSPECTION Yes NO ☒

Reason for special Inspection ?

Richard Nelson

ion *A. Bayle*

Quick Reporting Specifications

Tasks Filter 1 of 2 Download

New Row

Labor : Filler 1-2 of 2 [Download](#)

TRACK INSPECTION REPORTING FORM

Name

(Please Print)

Date _____

Page

1 of 1

Watchman

Inspected From

To

W.O Number

-1193069-

[illegible]

Item	COMMENT8
------	----------

No New defects Found

Were Switch In the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1193069 TEAM ONE - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA \ LTRAIL MTA - LTRAIL	Status	COMP
Asset		Priority	1
Alias		Work Type	PM
Location	CHAIN_MARK LT Rail Chain Markers	Crew	
Work Location		Warranty Situation Present?	N
Work Group	MTA527	Maintenance Alert?	<input type="checkbox"/>

Work Details Component <input type="text"/> Position <input type="text"/> Reason for Repair <input type="text"/> Work Accomplished <input type="text"/> Part Failure <input type="text"/> Parent WO <input type="text"/> Telematics Code <input type="text"/> Telematics Transaction <input type="text"/> GL Account J05-####-052	Total Planned Cost 0.00 Total Actual Cost 420.64 Repair Limit Amount <input type="text"/> Reported By MTACRON Reported Date 08/23/13 04:00:28 AM
---	--

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Labor 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	08/30/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WGREENWOOD	<input checked="" type="checkbox"/>	08/30/13	07:00:00	03:00:00	8:00	26.29	N	N/A

TRACK INSPECTION REPORTING FORM

Name W. Ishyaka T

Date 08-51-15

Page 1 of 1

(Please Print)

Watchman

R. Neilsen

W.O Number

1193080

Inspected From

Linthicum

To

CRIM 401

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch In the area of Inspected

Yes ☒

NO.

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO

SPECIAL INSPECTION

Yes.

NO

Reason for special Inspection ?

Walter W. B. Gunt

Track Inspector Signature

Supervisory Certification

ation *[Signature]*